Däte

Friday, 07/07/2006 8:59:10 AM

User:

Linda Lacelle

## **Process Sheet**

: CU-DAR001 Dart Helicopters Services Customer

Job Number : 27583 **Estimate Number** : 11799

P.O. Number

AIH: This Issue

: 07/07/2006

: NC : 15/06/2006

S.O. No. : NIA

: PURCHASED PARTS

**Part Number** 

Material

**Due Date** 

**Drawing Name** 

: D25251

**Drawing Number** 

: D2525 REV B

: SPACER KIT

**Project Number Drawing Revision** 

: N/A

: 30/06/2006

Qty:

20 Um:

Each

**Previous Run** Written By

Prsht Rev.

First Issue

Checked & Approved By

Comment

AIU:

: Est. B99.11.10

Re-format added Acid etch stepEC

**Additional Product** 

Job Number:



Seq. #:

**Description:** 

M6061T6R0750 1.0

Comment: Qty.:

0.0620 f(s)/Unit Total:

1.2400 f(s)

6061-T6 Round Bar .750"

2.0

Comment: CONVENTIONAL LATHE

6061-T6 Round Bar .750"



3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHIN



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

SECOND CHECK



4.0

QC8



20

20

HAND FINISHING

Comment: SECOND CHECK


HAND FINISHING RESOURCE #1





Comment: HAND FINISHING RESOURCE #1


Acid etch and Alodine as per QSI 005 4.1



6.0

Comparent: INSPECT WORK TO CURRENT STEP

INSPECT WORK TO CURRENT STEP



Date:

Friday, 07/07/2006 8:59:10 AM

Use: Linda Lacelle

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SPACER KIT

Job Number: 27583

Part Number: D25251

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

7.0

PACKAGING 1

PACKAGING RESOURCE #1



**Comment: PACKAGING RESOURCE #1** Identify and Stock Location: 5747



8.0

Job Completion

DC

DOCUMENT CONTROL







Comment: DOCUMENT CONTROL

Inspection Level 21



h 26-07.

Thursday, 6/15/2006 1:50:29 PM

User:

Kim Johnston

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 27583

**Estimate Number** 

: 11799

P.O. Number This Issue

: 6/15/2006

Prsht Rev. First Issue

: //

: NC

Type

S.O. No. :

: PURCHASED PARTS

Part Number

**Drawing Name** 

: D25251

**Drawing Number** 

: D2525 REV B : N/A

: SPACER KIT

**Project Number Drawing Revision** 

: B

Material

Material: 6061-76. Ø:750"

**Due Date** 

: 6/30/2006

Qty:

20 Um:

Each

**Previous Run** Written By

Checked & Approved By

Comment

Re-format added Acid etch stepEC

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

PURCHASING

PG 1.0

Comment: PURCHASING

Issue P/O:-- Make as per Dwg D2525

Material release note required

2.0



BAtch:

Comment: Qty.

20:0000 Each(s)



PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Recieive & Inspect for Transit Damage

Ensure Material Release Note is attached

4.0

**QG6** 

DIMENSIONAL CHECK

QC8



Comment: DIMENSIONAL CHECK

5.0

HAND FINISHING1

HAND FINISHING RESOURCE #1

Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

## **Dart Aerospace Ltd**

	WORK ORDER CH	WORK ORDER CHANGES						
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector		
	STEP	STEP PROCEDURE CHANGE	STEP PROCEDURE CHANGE By	STEP PROCEDURE CHANGE By Date	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Approval Mfg / Design Mgr		

NCR:			WORK ORI	DER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B	· · · · · · · · · · · · · · · · · · ·	Verification	Approval	Approval
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector
	ļ							

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA: N	I/C C	osed:	Date:

Thursday, 6/15/2006 1:50:29 PM Use: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: SPACER KIT Job Number: 27583 Part Number: D25251 Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT WORK TO CURRENT STEP Conversion. Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 7.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:\_ DOCUMENT CONTROL DC 8.0 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion 

Form: rprocess

Page 2

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHA	NGES					
DATE	STEP			Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector	
			-					

NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
<del></del>		Description of NC		Corrective Action Section B		Verification	Approval Design Mgr				
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Section C		Approval QC Inspector			
					l.						
	,										
	<u> </u>			*							
		<u> </u>		•							


Part No:	PAR #:	Fault Category:	NCR:	Yes No DQA:	Date: 06/07/13
NOTE: Date & initial all entries				QA: N/C Closed:	Date:



			• .	
DESIG	BW	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	•
CHEC	KED,	APPROVED	DRAWING NO.	REV. B
	HE	1 - 15	D2525 SHEET	1 OF 1
DATE			TITLE	SCALE
99.0	9.30		SPACER KIT	1:1
Α		95.12.22	NEW ISSUE	
В		99.09.30	REVISED MATERIAL	

RELEASED 199. 10. 12 Ke

PART NUMBER	THICKNESS T	QTY
D2525-1	0.750	1
D2525-3	0.250	1
D2525-5	0.125	4
D2525-7	0.063	0
D2525-9	0.032	0



SHOP COPY RETURN TO

MATERIAL: 5052-H32 (QQ-A-225/7) OR 1100 (QQ-A-225/9) NER CLED COPY OR 6061-T6 (QQ-A-225/8) OR 6061-T6 (QQ-A-200/8) NER CLED COPY FINISH: ACID ETCH AND ALODINE PER DART QSI 005 4. WITHOUT NOTICE

WORK ORDER 3

DART AEROSPACE LTD

Description: SPACER

Part Number: D2525 /

Inspection Dwg: D2525 , Rev: B

Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
,515	+.008	,516				
,750	±.0/0	.516 .752 .751				
.750 .750(f)	±,0/0	,751				
		•				
				,		
						·

Measured by:	90	Audited by:	Str	Prototype Approval:	NIA	_
Date:	06/07/11	Date:	66-07u11	Date:	- PII.	

				1
Rev	Date	Change	Revised by	Approved
A		New Issue	KJ/JLM	